

BAR 304 10MM

To protect the privacy of customers or suppliers of Salamander Jewelry.
We erased their address from this document.

Heat No		Thick (Dia)	Pcs	Wt	Chemical Composition(wt%)											Mechanical Property							
		(mm)		(kg)	C	Si	Mn	P	S	Ni	Cr	Mo	Cu	N				TS	YS	EL	RA	HRB	HRC
Spec		Min			x100	x100	x100	x1000	x1000	x100	x100	x100	x100	x10000				N/mm2	N/mm2	%	%		
		Max			3	100	200	45	30	800	1800			1000				620	310	30	40		
5S973		10.00		1039	2.0	34	167	37	27.8	806	1816	16	49	788				711	593	47	72	94	

Total: 1039

To protect the privacy of customers or suppliers of Salamander Jewelry.

We erased their address from this document.

TOLERANCE:h9

LENGTH TOLERANCE:0-50

Acc.to ASTM A276 Cond.A

The hardness conform to the requirement of raw material on NACE MR0103 and MR0175-A2.

The chemistry conform to the requirement of raw material on NACE MR0103 and MR0175-D1.

This inspection certificate is issued according to EN 10204 2.2

Remark:

Melted manufactured :Taiwan , Improved machining.
Solution annealed treatment:Acc. to ASTM A484.
Micro structure:good., Grain size:Acc.to ASTM E112.

SUPPLY CONDITION:

A:Annealed
B:Shot Blasted
C:As Casted
E:Reeled/Skin Pass
H:Precipitation Hardening
HR:Hot Rolled
I:Straightened
K:Cut Edge
L:Polished
M:Cold Rolled
P:Pickled
S:Shaved
V:Slit
W:Cut
X:Temper
CD:Cold Draw
CG:Centerless Ground
PL:Turned or Peeled

We have the following certifications

- 1.ISO9001:2015 Quality Management System
- 2.ISO/IEC 17025:2005 Laboratory Management System
- 3.PED & AD2000-Merkblatt W0
- 4.DNV · LR · ABS Classification Society certification
- 5.ISO14001:2015 Environment Management System
- 6.OHSAS 18001:2007 & TOSHMS Certificate

TEST METHOD :

CHEMICAL-ASTM E1806, E415, E1086, E1019

- 1.We hereby certify that material described herein has been manufactured and tested with satisfactory results in accordance with requirement of the above material specification.
- 2.We certify that the material is free from mercury and radiation contamination. Qualification No. of Taiwan Atomic Energy Committee:136
- 3.The Above Testing Results Relate Only To The Items Tested.
- 4.No welding repaired

To protect the privacy of customers or suppliers of Salamander Jewelry.

We erased their address from this document.